

## HOWARTH'S TANGED FIRMER CHISELS.



Size,	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	$\frac{5}{16}$	$\frac{3}{8}$	$\frac{7}{16}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in.
Per doz.	\$1 70	1 70	1 70	1 80	1 90	2 10	2 20	2 40	2 60	3 00	3 20	4 40	5 40	6 60	8 00
Bev'd edge, per doz.	3 30	3 30	3 30	3 50	3 50	3 80	4 00	4 20	4 60	4 80	6 80	7 80	9 80	10 20	
In Sets, $\frac{1}{4}$ to $1\frac{1}{2}$ (9 Chisels)														Per set	\$ 2 40
" $\frac{1}{8}$ to 2 (12 Chisels)														"	3 80
" $\frac{1}{4}$ to $1\frac{1}{2}$ (9 Chisels) Bevel Edge														"	3 60
" $\frac{1}{8}$ to 2 (10 Chisels) " Boxwood Oct. Handle														"	6 60

## TANGED LONG THIN PARING CHISELS.



Size,	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	$\frac{5}{16}$	$\frac{3}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in.	
Per doz.	\$3 00	3 00	3 00	3 10	3 40	3 80	4 30	4 60	5 60	7 60	9 20	10 80	13 40		
Bevel Edge, per doz.	5 40	5 40	5 40	5 50	5 80	6 20	6 70	7 10	8 00	11 20	12 80	15 60	18 20		
In Sets, $\frac{1}{4}$ to 2 (9 Chisels) Bevel Edge													Per set	\$ 8 00	
" $\frac{1}{8}$ to 2 (12 Chisels) " "													"	9 00	
" $\frac{1}{4}$ to 2 (10 Chisels) Boxwood Octagon Handle													"	10 50	
" $\frac{1}{8}$ to 2 (12 Chisels) " " "													"	10 50	

## TANGED MILLWRIGHT CHISELS.



Size.....	$\frac{1}{2}$	$\frac{3}{4}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	2 in.
Length.....	8	10	10	10	10	12 in.
Per doz.....	\$5 80	7 00	9 00	10 60	12 80	19 00

## TANGED TURNING CHISELS.



Six inch Blade.

Size,	$\frac{1}{4}$	$\frac{3}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{5}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in.
Per doz.....	\$2 40	2 60	2 90	3 20	3 60	4 00	4 60	5 80	7 40	9 00	10 60

## HOWARTH'S TANGED FIRMER GOUGES



Size,	$\frac{1}{8}$	$\frac{3}{16}$	$\frac{1}{4}$	$\frac{5}{16}$	$\frac{3}{8}$	$\frac{7}{16}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in
Length of blade,	$4\frac{5}{16}$	$4\frac{5}{16}$	$4\frac{3}{8}$	$4\frac{5}{8}$	$4\frac{3}{4}$	$4\frac{3}{4}$	$4\frac{3}{4}$	$5\frac{1}{4}$	$5\frac{1}{4}$	$5\frac{3}{8}$	$5\frac{5}{8}$	$6\frac{3}{8}$	$6\frac{5}{8}$	7	$7\frac{3}{8}$
Ground outside,															
per doz.....	\$2 10	2 10	2 10	2 30	2 30	2 40	2 60	2 80	3 10	3 50	3 70	5 20	6 40	7 80	9 60
Ground inside,															
per doz.....	\$2 20	2 20		2 40		2 70	2 90	3 20	3 60	3 80	5 40	6 60			
In sets of 9 Chisels, $\frac{1}{4}$ to $1\frac{1}{2}$ inch. Ground outside.....													per set	\$2 80	
" " 12 " $\frac{1}{8}$ to 2 "	"	"	"	"	"								"		4 40

## TANGED LONG THIN PARING GOUGES.



Size,	$\frac{1}{4}$	$\frac{3}{16}$	$\frac{1}{2}$	$\frac{5}{16}$	$\frac{3}{8}$	$\frac{7}{16}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in.
Length of blade,	$7\frac{7}{8}$	$8\frac{1}{8}$	$8\frac{5}{16}$	$8\frac{5}{8}$	$9\frac{1}{8}$	$9\frac{1}{4}$	$9\frac{1}{2}$	$10\frac{1}{10}$	$10\frac{1}{10}$	$10\frac{5}{8}$	11	$11\frac{3}{8}$	"		
Ground inside, per doz.	\$5 00	5 10	5 40	5 80	6 30	6 60	7 60	10 00	11 60	14 00	16 30				
In sets, $\frac{1}{4}$ to 2 (9 Chisels). Ground inside.....												per set	\$6 80		

## TANGED TURNING GOUGES.



Size,	$\frac{1}{4}$	$\frac{3}{8}$	$\frac{1}{2}$	$\frac{5}{8}$	$\frac{3}{4}$	$\frac{7}{8}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$1\frac{3}{4}$	2 in.			
Length,	$5\frac{3}{4}$	$5\frac{7}{8}$	6	$6\frac{1}{4}$	$6\frac{1}{4}$	$6\frac{3}{8}$	$6\frac{1}{2}$	$8\frac{2}{3}$	$7\frac{1}{2}$	$7\frac{1}{2}$	$7\frac{1}{2}$	"		
Per doz.,	\$3 10	3 50	3 80	4 20	4 90	5 60	6 30	8 20	10 70	12 60	15 40			

## TANGED MILLWRIGHTS' GOUGES.



Size,	$\frac{1}{2}$	$\frac{3}{4}$	1	$1\frac{1}{4}$	$1\frac{1}{2}$	$2$	in.
Ground inside, per doz.,	\$6 60	8 20	9 80	13 00	15 00	22 20	